



## Motion Computing Software Release Note

Name	<b>Intel USB 3.0 Drivers for Windows 7</b>
File Name	<b>Intel_USB_3.0_v1.0.8.251.zip</b>
Release Date	October 8, 2013
This Version	1.0.8.251
Replaces Version	All previous versions
Intended Users	<b>Motion C5t, F5t, C5te, F5te and J3600 users</b>
Intended Product	Motion C5t, F5t, C5te, F5te and J3600 Tablet PCs ONLY
File Size	5.3 MB
Supported Operating System	Windows 7 (32-bit and 64-bit)

### Fixes in this Release

- BSOD may occur when a USB printer is connected to USB3.0 port and the printer application is installed
- USB3.0 devices behind a USB3.0 HUB may disappear after system restart
- Some USB2.0 device connected behind USB3.0 port cannot enter to selective suspend correctly

### What's New In This Release

- N/A

### Known Issues and Limitations

- N/A

### Installation and Configuration Instructions

#### To install USB 1.0.8.251, perform the following steps:

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (setup.exe) and follow the prompts.

### Licensing

Refer to your applicable end-user licensing agreement for usage terms.