



Motion Computing Software Release Note

Name	Sierra Wireless 3G Watcher for Telstra
File Name	3G_Watcher_Telstra_2258.zip
Release Date	June 28, 2010
This Version	2258
Replaces Version	All previous versions
Intended Users	LE1700, C5/F5, J3400 users
Intended Product	LE1700, C5/F5, J3400 Tablet PCs ONLY
File Size	26 MB
Supported Operating System	<ul style="list-style-type: none">• Windows 7• Windows Vista (all versions except Windows Vista Home Basic)• Windows XP Tablet Edition 2005*, Version 2002, Service Pack 2 - Installed, Service Pack 3 - Installed. <p>* Tablet Edition 2005 is included with the free Service Pack 2 download. If you installed Windows XP Service Pack 2 on a Tablet PC, you now have Tablet Edition 2005.</p>

Fixes in this Release

- Latest Telstra certified Watcher connection manager from Sierra Wireless

What's New In This Release

- Latest Telstra certified Watcher connection manager from Sierra Wireless

Known Issues and Limitations

- Requires LE1700 BIOS AB16 or later
- Requires C5/F5 BIOS A11 or later
- Requires Dashboard 5026 or later

Installation and Configuration Instructions

To install this software:

1. Click download to save the latest **Sierra Wireless – Australia WWAN Software** to the directory of your choice.
2. **Unzip** the file to a location on your local drive.
3. Double-click **3G_Watcher_Telstra_xxxx.msi** and follow the prompts

Licensing

Refer to your applicable end-user licensing agreement for usage terms.