MK500 Rev 01.30.0016

[Part #: 5Cxxc50BenOS013016]

Contents

- <u>Description</u>
- <u>Platform SDK Compatibility</u>
- <u>Release Notes</u>
- <u>Components</u>
- Installation
- <u>Notes</u>

Description

Thank you for selecting Zebra as your mobility solution tool provider. This package provides a complete software image for the MK500/MK590 products, in an OSUpdate package and individual hex files for use with TCM

For the latest software updates, go to the <u>Support Central</u> web site and select Software Downloads.

For more information on Windows CE development and Enterprise Mobility platforms, please visit the <u>Products</u> Web site.

Thank you,

The Zebra Software Development Team

Back to Top

Platform SDK Compatibility

Windows CE Platform SDK v1.0 for MK500

Usage with older versions of the Platform SDK is not recommended.

Back to Top

Release Notes

Version v01.30.0016

1. Updated Fusion to version 3.00.2.0.044R for KRACK security issue.

Components

| Component | Filename |
|-----------------------------|-------------------------|
| Windows CE Operating System | MK500c50BenOS013016.hex |
| Application | MK500c50BenAP016.hex |
| Platform | MK500c50BenPL016.hex |
| Partition Table | MK500c50BenPT002.hex |
| Splash Screen | MK500c50BenSC001.hex |
| Monitor/Boot loader | MK500c50XenMO0152XX.hex |

Back to Top

Installation

Installation can be accomplished by either using a MicroSD card are copying the installation files to the devices Temp folder and installing from there.

MicroSD Card Installation

- 1) Extract all files and folders from 5Cxxc50BenUP013016.zip
- 2) Copy the OSUpdate folder and all subfolders and files to the root of the MicroSD cards
- 3) Insert the MicroSD card into the MK500/MK590
- 4) From the MK500/MK590 execute $i_{\ell}^{1/2}$ My Device $i_{\ell}^{1/2}$ from the desktop
- 5) Open the $i_{\xi}^{1/2}$ Storage Card $i_{\xi}^{1/2}$ folder
- 6) Open the OSUpdate folder
- 7) Double tap on the file $i_{\zeta}^{1/2}$ MK500c50BenColor_SD.lnk $i_{\zeta}^{1/2}$
- 8) Installation will begin and the device will reset when complete

Temp Folder Installation

- 1) Extract all files and folders from 5Cxxc50BenUP013016.zip
- 2) Establish an ActiveSync session
- 3) Copy the OSUpdate folder and all subfolders and the devices \Temp folder
- 4) From the MK500/MK590 execute $i_{\ell}^{1/2}$ My Device $i_{\ell}^{1/2}$ from the desktop
- 5) Open the $i_{\ell}^{1/2}$ Temp $i_{\ell}^{1/2}$ folder
- 6) Open the OSUpdate folder
- 7) Double tap on the file $i_{\xi}^{1/2}$ MK500c50BenColor_Temp.lnk $i_{\xi}^{1/2}$
- 8) Installation will begin and the device will reset when complete

Back to Top

Notes

1. None

Back to Top

Last revised: August 23, 2011

Copyright (c) 2003-2011