



Release Notes – Zebra Android 11

11-19-13.00-RG-U06-STD-GSE-04 Release (GMS)

Highlights

This Android 11 GMS release 11-19-13.00-RG-U03-STD-GSE-04 covers ET40S, ET40L, ET45S and ET45L series product. Please see, device compatibility under Addendum Section for more details.

Software Packages

| Package Name | Description |
|--|--|
| GO_FULL_UPDATE_11-19-13.00-RG-U06-STD-GSE-04.zip | Full Update Package |
| GO_DELTA_UPDATE_11-19-13.00-RG-U03-STD_TO_11-19-13.00-RG-U06-STD.zip | Delta package from previous release 11-19-13.00-RG-U03-STD |

Security Updates

This build is Compliant up to [Android Security Bulletin](#) of May 05, 2023.

LifeGuard Update 11-19-13.00-RG-U06

- LifeGuard Update 11-19-13.00-RG-U06 contains security updates only.
This LG patch is applicable for 11-19-13.00-RG-U06-STD-GSE-04 version

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 11-19-13.00-RG-U03

- LifeGuard Update 11-19-13.00-RG-U03 contains security updates only.
This LG patch is applicable for 11-19-13.00-RG-U00-STD-GSE-04 version

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 11-19-13.00-RG-U00

- This LG patch is applicable for 11-17-20.00-RG-U03-STD-GSE-04 version

Updated below mentioned components:

| | |
|------------------------|-------------------------|
| OSx version - | SD6375.110.20.34 |
| License Agent Version- | 6.0.45.5.0.3 |
| WLAN Version- | FUSION_SA_5_4.0.0.004_R |
| Firmware Version- | 18.35.387.23.1308.11 |
| Zebra Volume Control - | 3.0.0.84 |

- **New Features**

- None

- **Resolved Issues**

- SPR-48491-Enabling the 5G support for Reliance Jio Network

- **Usage Notes**

- None

LifeGuard Update 11-17-20.00-RG-U03

- LifeGuard Update 11-17-20.00-RG-U03 contains security updates only.

This LG patch is applicable for 11-17-20.00-RG-U00-STD-GSE-04 version.

- **New Features**

- None

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 11-17-20.00-RG-U00

- **New Features**

- MXMF
 - Please refer to MXMF [Version History](#) for more information on new features added for MXMF.
 - Added accessibility settings to reduced settings mode in MXMF
- Full functionality of Wireless Analyzer is available with this BSP Image. Prior images only supported Beta version of Wireless Analyzer.
- Battery Manager
 - Zebra Charge Manager Parameters are added to list of parameters that battery manager displays to the user.
- RXLogger
 - Added additional option in Snapshot module to include WAN dumphsys functionality
 - Added feature to reduce interruption to logging when user accidentally deletes the RXLogger folder in the device.
- Scanner Framework
 - USB scanner and Cradle support added
 - Free-form OCR feature support added
 - Free-Form Image Capture feature support added
 - New OCR Wedge Features added: License plate, Identification Documents, Vehicle Identification Number (VIN), Tire Identification Number (TIN), Shipping Container ID, Meter
 - Document Capture feature support added
 - Barcode Highlighting Feature support added
- Zebra Camera Application is introduced to ET40/ET45 devices with current version of SW. Features supported include
 - Consumer phone style UI for easier workforce adoption
 - Built-in QR Code decode for accessing internal or external websites
 - Dirty lens detection and warning to reduce the chance of taking photos with obstructed lens
 - Integrated Google Lens feature
 - Better image quality in wider variety of lighting conditions
- Added functionality to Zebra Bluetooth Manager to enable or disable the default silent pairing option as out of box it is enabled always and no option was available to disable it previously.
- DataWedge now has Zebra Camera added to the disabled App list so DW will not get enabled when camera App is running.

○ Resolved Issues

- SPR-47094 – Resolves an issue where, ET40 does not connect to AirWatch Server when device is connecting to the network through a Proxy PAC file.
- SPR-46408 – Resolves an issue where, StageNow Not showing downloading pop up when downloading OS update file from custom ftp server
- SPR-46162 – Resolves an issue where, USB keyboard stop working when using USBMgr, a parameter called “Access device storage from PC via USB” is set to disable.
- SPR-46418 – Resolves an issue where, License through Proxy is failing from StageNow
- SPR-47128 – Resolves an issue where, App installed manually to device failed to uninstall via StageNow/EMDK uninstall from App Manager
- Fixed an issue where, using wireless insights concurrently with WLAN voice calls not supported.
- Fixed an issue where, A customer using a proxy PAC file which has isInNet() JavaScript API to direct the traffic to intranet vs extranet or similar functionality will not be able to establish a connection to the desired endpoint without switching to an alternate API.
- Fixed an issue where, “ping” functionality of “Wireless Analyzer” will not be supported for 802.11ax.
- SPR-47903 – Resolves an issue where, location services crash triggers a device rescue party mode.
- SPR-47767 – Resolves an issue where, incorrect screen size information shown when queried through benchmark SW.
- SPR-47707 – Resolves an issue where, regular ANRs seen when DW and EMDK was used with work profile
- SPR-47670 – Resolves an issue where, application requiring large heap size crashed
- SPR-47926 – Resolves an issue where, available SSID's are not always showing up / connecting
- SPR-47856 – Resolves an issue where, occasionally WLAN disconnects and does not connect back especially with ISP provided Aps.
- SPR-47768 – Resolves an issue where, WLAN reconnection not successful when the device leaves a known network for longer periods of time.
- Fixed an issue where, when enterprise reset is done on a device where MDNA license is enabled, persisted configuration settings for Zebra Volume Control and Bluetooth Manager which is persisted using the Persist Manger need to be re-configured after the enterprise reset.

○ Usage Notes

- None

Version Information

Below Table contains important information on versions

| Description | Version |
|----------------------|--|
| Product Build Number | 11-19-13.00-RG-U06-STD-GSE-04 |
| Android Version | 11 |
| Security Patch level | May 05, 2023 |
| Component Versions | Please see Component Versions under Addendum section |

Device Support

The products supported in this release are ET40S, ET40L, ET45S and ET45L series product. Please see device compatibility details under Addendum Section. ***This SW is not approved Verizon carriers yet and once approved updated release notes with the supported device part numbers would be published.***

Known Constraints

- Due to Google security constraint, products introduced with Android 11 as the base OS limits the “adb push” command to copy files only to /data partition hence pushing files directly to /enterprise or sub folder of enterprise partition using “adb push” command will not be supported. Please see respective product documentation for further details on path changes related to this constraint.
- In the current version of SW Released, Wi-Fi Hotspot feature is disabled. This is expected to get enabled back in future maintenance release.
- When ET40/ET45 is used with a workstation docking cradle or POS Hub we recommend keeping the ethernet port enabled as per default out of the box condition. Upcoming Maintenance releases will address this issue which will allow to disable ethernet port if desired. Please note that this restriction does not apply for charge only cradles.
- “Messages for Web” feature is not fully supported with the current version of SW as after a device reboot it does not allow to pair with another browser unless a factory reset is done.
- Battery manager charging status is shown as “Not Charging” once the battery is fully (100%) charged instead of showing as “Full” once Zebra Charge Manager feature is enabled.
- Camera Manager CSP is not supported on ET40/ET45 Devices.

- Device display will be force rotated to landscape once the device is placed in a cradle. If this needs to be disabled, contact your Zebra support channel for more information.
- Current SW Released will not support “Wind Tre Business” SIM cards due to known stability issue. Support for this SIM would be added in subsequent maintenance releases.

Important Links

- [Installation and setup instructions](#) (if the link does not work, please copy It to browser and try)
- [Zebra Techdocs](#)
- [Developer Portal](#)

Addendum

Device Compatibility

This software release has been approved for use on the following devices.

NOTE:

This SW is not approved Verizon carriers yet and once approved updated release notes with the supported device part numbers would be published.

| Device Family | Part Number | | Device Specific Manuals and Guides |
|---------------|---|---|------------------------------------|
| ET40S | ET40AA-001C1B0-NA ET40AA-001C1B0-FT ET40AA-001C1B0-A6 ET40AA-001C1B0-IN ET40AA-001C1B0-TR | ET40AA-001C1B0-XP ET40AA-001D1B0-A6 ET40AA-001D1B0-NA ET40AA-001C1BM-NA | ET40 Home Page |
| ET40L | ET40AB-001C1B0-NA ET40AB-001C1B0-FT ET40AB-001C1B0-A6 ET40AB-001C1B0-IN ET40AB-001C1B0-TR ET40AB-0H1C1B0-A6 ET40AB-0H1C1B0-FT | ET40AB-0H1C1B0-IN ET40AB-0H1C1B0-NA ET40AB-0H1C1B0-TR ET40AB-001D1B0-A6 ET40AB-001D1B0-NA ET40AB-001C1BM-NA ET40AB-0H1C1BM-NA | |
| ET45S | ET45CA-101D1B0-A6 ET45CA-101D1B0-IN ET45CA-101D1B0-ID ET45CA-101D1B0-TR | ET45CA-101D1B0-XP ET45BA-101D1B0-FT ET45BA-101D1B0-NA ET45BA-101D1BM-NA | ET45 Home Page |
| ET45L | ET45CB-101D1B0-A6 ET45CB-101D1B0-IN ET45CB-101D1B0-TR | ET45BB-101D1B0-FT ET45BB-101D1B0-NA ET45BB-1H1C1B0-FT | |

| | | | |
|--|---|--|--|
| | ET45CB-101D1B0-XP ET45CB-1H1C1B0-A6 ET45CB-101D2B0-A6 ET45CB-101D2B0-IN ET45CB-101D2B0-TR | ET45BB-1H1C1B0-NA ET45BB-101D2B0-FT ET45BB-101D2B0-NA ET45BB-101D1BM-NA ET45BB-101D2BM-NA ET45BB-1H1C1BM-NA | |
|--|---|--|--|

Component Versions

| Component / Description | Version |
|---------------------------|--|
| Acoustic Profiles | ET4XS: General: ET4XS-R-1.2 Cellular: N/A ET4XL: General: ET4XL R-2.2 Cellular: N/A |
| Audio | 0.1.0.0 |
| AnalyticsMgr | 10.0.0.1002 |
| Android SDK Level | 30 |
| Base Band Version | MPSS.HI.4.3.1-01282-MANNAR_GEN_PACK-1 |
| Battery Manager | 1.4.0 |
| Bluetooth Pairing Utility | 3.27 |
| Camera Tuning | Camera 0: 02.C.OV13B10.08 Camera 1: 02.C.GC5035.04 |
| DataWedge | 11.4.42 |
| EMDK | 11.0.133.4033 |
| Files | aml_doc_310851020 |
| GMS | [11_202203] |
| License Manager | License Manager: 6.0.13 License Agent Version: 6.0.45.5.0.3 |
| Linux Kernel | 5.4.147 |
| MXMF | 11.6.0.17 |
| NFC | PN7160_AR_11.02.00 |

| | |
|----------------------------|--|
| OEM info | 9.0.0.699 |
| OSX | SD6375.110.20.34 |
| RXLogger | 7.75.3.24 |
| Scanning Framework | 37.7.4.0 |
| StageNow | 11.6.0.0 |
| Touch Panel (FW) | 7.0.0.1.10.1.0.5 |
| WLAN | Version: FUSION_SA_5_4.0.0.004_R Firmware Version: 18.35.387.23.1308.11 |
| Wireless Analyzer | WA_A_2_7.4.0.025_R Wireless Analyzer: 3.2.13 |
| WWAN | HW MBN: HW_DEFAULT: 0AE10104 SW MBN: SIM 0: ROW_Commercial |
| Zebra Bluetooth | Service: 11.2.1 Settings: 11.0.5 |
| Zebra Camera | 2.0.24 |
| Zebra Data Service | 10.0.4.1263 |
| Zebra Volume Control | 3.0.0.84 |
| Chrome and webview version | 97.0.4692.98 |

Revision History

| Rev | Description | Date |
|-----|-----------------|--------------|
| 1.0 | Initial release | May 17, 2023 |