

Release Notes – Zebra Android 13

13-28-24.00-TG-U00-STD-GSE-04 Release (GMS) (MANDATORY UPDATE)

Highlights

This Android 13 GMS release 13-28-24.00-TG-U00-STD-GSE-04 covers ET4X series product. Please see device compatibility under Addendum Section for more details.

Software Packages

| Package Name | Description |
|--|---|
| GO_FULL_UPDATE_13-28-24.00-TG-U00-STD-GSE-04.zip | Full Update Package |
| GO_DELTA_UPDATE_13-27-21.00-TG-U00- STD_TO_13-28-24.00-TG-U00-STD.zip | Delta package from previous release 13-27-21.00-TG-U00-STD-GSE-04 |

Security Updates

This build is Compliant up to Android Security Bulletin of March 01, 2024.

LifeGuard Update 13-28-24.00-TG-U00-STD-GSE-04

This LG patch is applicable for 13-27-21.00-TG-U00-STD-GSE-04 version.

New Features

• None

Resolved Issues

• SPR-52928 Ensures Proximity Sensor operates without user data being transferred.

Usage Notes

- MANDATORY: This patch must be applied to devices to maintain EU Compliance. Future releases will include this update.
- Affected model: ET45CA.



Known Constraints

• None

LifeGuard Update 13-27-21.00-TG-U00-STD-GSE-04

This LG patch is applicable for 13-23-30.00-TG-U10-STD-GSE-04 version.

New Features

- Scanner Framework
 - Added support to Zebra POS Scanner/Scale.
 - Added support for COPE mode.

Zebra Data Services

- Added feature to measure battery consumption per application.
- MX 13.2
 - Feature vibrate icon enable/disable allows the device admin to control the state and status of the vibrate icon on status bar of the device. Usage details: https://techdocs.zebra.com/mx/audiovoluimgr/.
 - Added a new MX feature which allows to show/hide the taskbar shortcuts which appear on the bottom of the screen in large screen UI.
 - Added new MX feature to enable/disable write access to Android/data and Android/obb folders of the device, when connected via MTP (Media Transfer Protocol).

• UI Manager

- Added a feature to control Large-screen Taskbar usage, which displays recent and pinned apps, plus a link to the app library.
- Added a feature to control usage of the Active App List UI in the Notification panel on the device, potentially allowing the user to terminate apps running on the device.
- Identify external keyboard names using wildcard characters.
- Disabled MHS and setting for VZW Carrier.

DataWedge

- Added support for Digital Link parsing for GS1 barcodes in DataWedge
- ZVA
 - Smart leash feature support for device tracker application.



• Added support device discovery, connection state.

Wireless Analyzer

• Improved analysis reports and error handling for Roaming and Voice Features, support for WPA3, 6E and MultiBSSID bug fix.

Resolved Issues

- SPR-51099 Fixed an issue where user is unable to scan in the Google Setup Wizard screen.
- SPR-51746 Fixed an issue where DataWedge is getting disabled when an EMDK scanning application is launched soon after a reboot.
- SPR-52011 Resolved an issue wherein a delay in processing EMDK profiles were observed.
- SPR-51954 Resolved an issue wherein location or other configuration were not working without cope mode enabled in device.
- SPR-51686 Resolved an issue wherein FileMgr was reporting download completed before the file downloaded successfully.
- SPR-51491 Resolved an issue wherein MX Display configuration caused screen to dim but not time out.
- SPR-51888 Resolved an issue wherein "Shift" + "Force State OFF" mapping was not working.
- SPR-52138 Resolved an issue wherein DM session authentication failure observed with Verizon carrier.
- SPR-50739 Resolved issue wherein hardware picklist is not working in NG Simulscan Multibarcode mode.
- SPR-51297 Corrected device transport type for BLE connections.

Usage Notes

• None

Known Constraints

None

LifeGuard Update 13-23-30.00-TG-U10-STD-GSE-04

This LG patch is applicable for 13-23-30.00-TG-U02-STD-GSE-04 version

New Features

- None.
- Resolved Issues



• None.

• Usage Notes

• None

LifeGuard Update 13-23-30.00-TG-U02-STD-GSE-04

This LG patch is applicable for 13-23-30.00-TG-U00-STD-GSE-04 version.

- New Features
 - None.
- Resolved Issues
 - None.
- Usage Notes
 - None.

LifeGuard Update 13-23-30.00-TG-U00-STD-GSE-04

This LG patch is applicable for 13-23-30.00-TG-U00-STD-GSE-04 version.

Updated below mentioned components: Chrome and WebView 115.0.5790.166 GPSU October-2023 Mainline

- New Features
 - none.
- Resolved Issues
 - none.
- o Usage Notes
 - o none.



LifeGuard Update 13-23-17.00-TG-U00-STD-GSE-04

This LG patch is applicable for 13-23-17.00-TG-U00-STD-GSE-04 version.

Updated below mentioned components:

| OSx version | QCT6375.130.13.8.14 |
|-------------------|------------------------------------|
| Bluetooth Pairing | Utility Application Version: 6.3.0 |
| | Build version: 5.3 |
| Data Wedge | 13.0.121 |
| EMDK | 13.0.7.4307 |
| MXMF | 13.1.0.65 |
| Scanning Framew | ork 39.67.3.0 |
| License Manager | 6.0.29 |
| License Agent Ve | |
| WLAN Version | FUSION_SA_5_1.2.0.001_T |
| | |

• New Features

- UI Manager adds the ability to Show/hide Immersive Mode pop-up warning.
- Pop-up suppression and USB controlling Application.
- Allows capture of either a barcode or OCR (single word) by centering the desired target with the aiming crosshair or dot. Supported on both Camera and Integrated Scan Engines.

• Resolved Issues

- SPR51331 Resolved an issue where Scanner remained in DISABLED status after suspending and resuming the device.
- SPR51244/51525 Resolved an issue where ZebraCommonIME/Data Wedge getting set as primary Keyboard.
- SPR51101 -- Resolved an issue wherein few chars were getting missed in decoded barcode data while performing scanning in HID mode.
- SPR51467 Resolved an issue wherein VoLTE config for a certain carrier was not connecting to 5G.
- SPR48241 Resolved an issue wherein System UI was crashing with MobileIron's DPC launcher on long pressing of back button from keyboard.
- SPR50986 Resolved an intermittent issue wherein Datawedge profile with UPCA settings was not getting created programmatically.
- SPR-51480 Resolved an issue wherein Shift key functionality with ForceStateOFF was not working.

• Usage Notes

None



Version Information

Below Table contains important information on versions

| Description | Version |
|----------------------|--|
| Product Build Number | 13-28-24.00-TG-U00-STD-GSE-04 |
| Android Version | 13 |
| Security Patch level | March 01, 2024 |
| Component Versions | Please see Component Versions under Addendum section |

Device Support

The products supported in this release are ET40S, ET40L, ET45S and ET45L series product. Please see device compatibility details under Addendum Section.

New Features

- In A13 Quick setting UI has changed.
- In A13 Quick setting UI QR scanner code option is available.
- Initial Beta Release of Zebra Showcase App (Self Updatable) explores the latest features and solutions, a platform for new demos built on Zebra Enterprise Browser.
- DWDemo has moved to ZConfigure folder.

Resolved Issues

- SPR48680 Resolved an issue with Video conference over WEB RTC (Real Time Communication)
- SPR48197 Resolved an issue with Device freeze and reboot after a specific SIM is inserted.
- SPR50196 Resolved an issue with Display randomly blinks off on when in workstation cradle.
- SPR50306 Resolved an issue with intermittently fail to emit scan beam.
- SPR50527 Resolved an issue with reboot with specific carrier.
- SPR51037 Resolved an issue with Scan beam issue.
- SPR50307 Resolved an issue with unexpected reboots.
- SPR50571 Resolved an issue with Manual Screen Rotation Doesn't Rotate the Screen.
- SPR50667 Resolved an issue with Bluetooth disconnections with payment pin terminal.
- SPR50862 Resolved an issue with wrong APN proxy & mms setting for Swisscom fix porting.
- SPR47670 Resolved an issue with Application crashing.
- SPR47886 Resolved an issue with Synaptic FW
- SPR48803 Resolved an issue with MX UI Setting Lock Override Button throws exception Feature is not supported.
- SPR50166 Resolved an issue with Verizon network connection.
- SPR48504 Resolved an issue with access internal site by URL.
- SPR47061 Resolved an issue with MX APK Upgrade.
- SPR47856 Resolved an issue with WLAN disconnection .



- SPR47926 Resolved an issue with Available SSID's are not always showing up / connecting.
- SPR50640 Resolved an issue with DUT not able to ping Hostname if changed MX 11.6
- SPR51205 Resolved an issue with DUT seems to have same BT SCO 4kHz
- SPR47128 Resolved an issue with App installed manually to device failed to uninstall via Stagenow/ EMDK
- SPR47285 Resolved an issue with TN28 enter to Rescue Party mode after called the reboot from MX under DO mode of China Unicom MDM.
- SPR47767 Resolved an issue with ET45 incorrect screen size information shown.
- SPR47903 Resolved an issue with ET40 location services crashing.
- SPR47925 Resolved an issue with ET45 display reverting to landscape mode when docked.
- SPR48182 Resolved an issue with SOTI script reset password is setting screen lock to Password instead of PIN.
- SPR48705 Resolved an issue with ET45 rotating when in cradle.
- SPR51024 Resolved an issue with ET4x Lock Override button is not working.
- SPR50755 Resolved an issue with decommission battery error.
- SPR47768 Resolved an issue with WLAN reconnection issue.
- SPR51024 Resolved an issue with ET4x Lock Override button is not working.

Usage Notes

None

Known Constraints

- DHCP Option 119 & Auto PAC Proxy feature is currently not supported in this release. Zebra is working on enabling these 2 features in future Android 13 releases.
- Ethernet configuration static to DHCP is not supported via Mx in this release.
- To apply Delta OTA packages, use StageNow/MDM solution. Delta OTA packages are not supported in Recovery mode.
- Data will not be Persisted if we upgrade to this A13 image from A11 image with greater SPL Version.
- Upgrading to this A13 OS version from A11 will not work on 1mbps network until this issue is fixed in A11 image .
- In mirror mode if device and external display resolution are different, UI flicker will be observed when Undock/ dock the device.
- OTA update from AB /storage/usbotg/ will take more than 2 minutes to initiate.
- In landscape mode when display and font is set to maximum, Lock icon will not be visible .
- Wireless insights and wireless analyzer are not supported in this release. will be supported in a later SW Update
- Workstation Connect is not supported on this release, compatibility with this solution will be introduced on an upcoming release.
- Zebra apps do not support Android Work Profiles or any COPE Mode features. Zebra is working on enabling these features in future Android 13 releases.

Important Links

- Installation and setup instructions (if the link does not work, please copy It to browser and try)
- Zebra Techdocs
- Developer Portal



Addendum

Device Compatibility

This software release has been approved for use on the following devices.

| Device Family | Part Number | | Device Specific Manuals and Guides |
|------------------|---|---|---------------------------------------|
| ET40S | ET40AA-001C1B0-NA ET40AA-001C1B0-FT ET40AA-001C1B0-A6 ET40AA-001C1B0-IN ET40AA-001C1B0-TR ET40AA-001C1B0-XP ET40AA-001C1BM-NA | ET40AA-001C2B0-A6 ET40AA-001C2B0-TR ET40AA-001C2B0-NA ET40AA-001C2BM-NA ET40AA-001C2BM-A6 | |
| ET40L | ET40AB-001C1B0-NA ET40AB-001C1B0-FT ET40AB-001C1B0-A6 ET40AB-001C1B0-IN ET40AB-001C1B0-TR ET40AB-0H1C1B0-TR ET40AB-0H1C1B0-FT ET40AB-0H1C1B0-IN ET40AB-0H1C1B0-NA ET40AB-0H1C1B0-TR ET40AB-001C1BM-NA | ET40AB-001C1BM-IN ET40AB-001C1BM-A6 ET40AB-001C2B0-A6 ET40AB-001C2B0-TR ET40AB-0H1C2B0-A6 ET40AB-0H1C2B0-NA ET40AB-0H1C2BM-NA ET40AB-001C2BM-NA ET40AB-001C2BM-NA | ET40 Home Page |
| ET45S | ET45CA-101D1B0-A6 ET45CA-101D1B0-IN ET45CA-101D1B0-TR ET45CA-101D1B0-TR ET45CA-101D1B0-XP ET45BA-101D1B0-FT ET45BA-101D1B0-NA ET45BA-101D1BM-NA | ET45CA-101D2B0-A6 ET45CA-101D2B0-TR ET45CA-101D1BI-IN ET45BA-101D2B0-NA ET45BA-101D2BM-NA | ET45 Home Page |
| ET45L | ET45CB-101D1B0-A6 ET45CB-101D1B0-IN ET45CB-101D1B0-TR ET45CB-101D1B0-TR ET45CB-101D1B0-XP ET45CB-1H1C1B0-A6 ET45CB-101D2B0-A6 ET45CB-101D2B0-IN | ET45CB-101K2B0-A6 ET45BB-101K2B0-NA ET45CB-1H1C2B0-A6 ET45CB-101D1BI-IN ET45BB-101K2B0-FT ET45BB-1H1C2B0-NA ET45BB-1H1C2BM-NA | |



| ET45CB-101D2B0-TR ET45BB-101D1B0-FT | |
|--|--|
| | |

Component Versions

| Component / Description | Version |
|---------------------------|---|
| Acoustic Profiles | General:ET45-T-3.1 Cellular: ET45-T-3.1 |
| Audio | 0.12.0.0 |
| AnalyticsMgr | 10.0.0.1008 |
| Android SDK Level | 33 |
| Base Band Version | MPSS.HI.4.3.4-00572-MANNAR_GEN_PACK-1 |
| Battery Manager | 1.4.7 |
| Bluetooth Pairing Utility | Application Version: 6.3.11 Build Version: 6.1 |
| DataWedge | 13.0.218 |
| EMDK | 13.0.13.4713 |
| Files | version 13 |
| GMS | 13_202304 |
| License Manager | 6.1.3 |
| MXMF | 13.2.0.32 |
| NFC | PN7160_AR_11.02.00 |
| OEM info | 9.0.0.1005 |
| OSX | QCT6375.130.13.19.15 |
| RXLogger | 13.0.12.27 |
| Scanning Framework | 41.17.8.0 |
| StageNow | Application version: 13.0.0.0 Build Version: 13.2.0.32 |
| Touch Panel (FW) | Touch Version: 7.0.0.1.10.1.0.7 Mode: Finger only |
| Zebra Bluetooth | 13.4.1 |



| Chrome and WebView | 115.0.5790.166 |
|--------------------|-----------------------|
| GPSU | October-2023 Mainline |

Revision History

| Rev | Description | Date |
|-----|-----------------|----------------|
| 1.0 | Initial release | April 16, 2024 |