

Release Notes – Zebra Android 11

11-27-20.00-RG-U00-STD-GRT-04 Release (GMS)

Highlights

This Android 11 GMS release 11-27-20.00-RG-U00-STD-GRT-04 covers TC15 series product. Please see, device compatibility under Addendum Section for more details.

Software Packages

Package Name	Description
GR_FULL_UPDATE_11-27-20.00-RG-U00-STD-GRT-04.zip	Full Update Package
GR_DELTA_UPDATE_11-23-23.00-RG-U00-STD_TO_11-27-20.00- RG-U00-STD.zip	Delta package from previous release 11-23-23.00-RG-U00-STD

Security Updates

This build is Compliant up to Android Security Bulletin of August 05, 2023.

LifeGuard Update 11-27-20.00-RG-U00

This LG patch is applicable for 11-23-23.00-RG-U00-STD-GRT-04 version

Updated below mentioned components:

OSx version - SD6375.110.25.39

MXMF 13.1.0.14

License Manager: 6.1.1

License Agent Version: 6.1.7.5.0.3

Scanning Framework - 37.9.24.0

Bluetooth Pairing Utility 3.29

DataWedge 11.4.310

EMDK 11.0.141.4041

Linux Kernel 5.4.233

OEM info 9.0.0.828 RXLogger - 7.75.5.36

New Features

- BQR extn Support to Device Tracker app
- Zebra Recovery Protection
- Added support for ADB command for Scanner SN and Camera SN.
- Added support of AccessMgr support removal for Analytics provider.

1



- Added support to collect the SIM EID.
- Added support to allow device central to publish data via ZDPI.
- Disabled all NFC HAL services for Federal SKU1
- Added support for service mode.
- Added support for Detection of Fatal exceptions.
- Two applications which are to be launched in split screen mode in a customized split ratio automatically after reboot.
- Single application to be launched in full screen mode automatically after reboot.

Resolved Issues

- SPR-50166 Resolved an issue where device not connecting using custom Verizon APN.
- SPR-50571 Resolved an issue Manual Screen Rotation Doesn't Rotate The Screen.
- SPR-46893 Resolved an issue StageNow GPRS Manager failed to set APN as a default.
- SPR-50527 Resolved an issue where reboot randomly with Windtree simcard.
- SPR-50146 Resolved an issue unable to remap PTT button to Power.
- SPR-50420 Resolved an issue fix reboot isssue

Usage Notes

None

LifeGuard Update 11-23-23.00-RG-U00

This LG patch is applicable for 11-19-13.00-RG-U00-STD-GRT-04 version

Updated below mentioned components:

OSx version - SD6375.110.21.37

Acoustic Profiles- TC15:

General:TC15-R-1.3 Cellular: TC15-R-1.1

MXMF 11.9.0.18

Camera Tuning- Camera 0:01.C.OV13B10.18

Camera 1:01.C.GC5035.04

License Manager: 6.1.1

License Agent Version: 6.1.3.5.0.3

NFC- NFC_NCIHALx_AR18C0.11.02.00

 Zebra Camera 2.04.102

 Scanning Framework 37.9.12.10

 StageNow 11.9.0.1

 RXLogger 7.75.5.31

 Zebra Data Service 10.0.4.1263

New Features

 Added support to configure whether LED should be on when it's charging to indicate charging status, else turn off



- Added Zebra Charge Manager support Provides an interface to administrators to configure battery charging level \$ charging time to helps improve battery longevity.
- Supporting Enhanced Connection manager for device to automatically switch between Wi-Fi and Cellular based on signal strengths
- USB Manager adds the ability to Configure USB Host Mode with rules for connecting peripherals without prompting the device user, for granting apps permission to access peripherals and for autolaunching apps on connection.
- Add support of Free-Form OCR powered by Google ML Kit using Text Recognition v2 (Beta) API
- Adding support MX CSP 11.9 for WWAN/LAN connection manager Adding support MX CSP 11.9 for Incoming/Outgoing call blocking through Admin

Resolved Issues

- SPR-48221 Resolved an issue wherein devices would goto rescue party mode intermittently.
- SPR-50306 Fix camera evict rule check logic issue
- SPR 48429 Resolved an issue wherein user was able to get access to settings menu even with EHS launcher enabled while device was having low battery.
- SPR 48803 Resolved an issue where MX UI Setting LockOverrideButton feature was throwing Feature not supported error.
- SPR-48680 Resolved an issue where ET40/ET45/TC53/TC58 Video conference over WEB RTC (Real Time Communication) interpreting solution not working - no picture of the other participant (the interpreter) visible on the Zebra device
- SPR-48197 Resolved an issue where Device freezes and reboots after a specific SIM is inserted
- SPR-48686 Resolved an issue where screen rotation locking after waking from sleep
- SPR 48404 Resolved an issue wherein Keystroke Action Key in Datawedge was not working as expected.
- SPR 47994 Resolved an issue wherein ZDM was consuming more memory resulting in delayed response to access Privileged settings.
- SPR 47457 Resolved an issue wherein EMDK's ProcessProfile API would fail if it was repeatedly
- SPR 48005 Resolved an issue wherein user was not able to set WIFI password that includes "\" using Stage Now
- SPR 47819 Resolved an issue wherein user was not able to set Display size to 'Large' using Stage Now
- SPR-48051 Resolved an issue regarding StageNow where FileMgr CSP is not working for A11
- SPR 48128 Resolved an issue wherein Access Manager CSP was reporting "Unable to Initialize" error while using WFC.
- SPR 50225 Resolved an issue where beam scan does not work with presentation mode and stay awake enabled
- SPR-47558 Implemented the Support of Enabling/Disabling Captive Portal through MX

Usage Notes

None

LifeGuard Update 11-19-13.00-RG-U00

This LG patch is applicable for 11-14-13.00-RG-U00-STD-GRT-04 version

Updated below mentioned components: OSx version -

SD6375.110.20.34



Acoustic Profiles- TC15:

General:TC15-R-1.3 Cellular: TC15-R-1.1

MXMF 11.9.0.18

Camera Tuning- Camera 0:01.C.OV13B10.18

Camera 1:01.C.GC5035.04

License Manager: 6.1.1

License Agent Version: 6.1.3.5.0.3

NFC- NFC_NCIHALx_AR18C0.11.02.00

Zebra Camera- 2.04.102 Zebra Data Service- 10.0.7.1001

New Features

None

Resolved Issues

SPR-48491-Enabling the 5G support for Reliance Jio Network

Usage Notes

None

LifeGuard Update 11-14-13.00-RG-U00

New Features

- Please refer to MXFS Version History for more information on new features added for MXMF.
- Added accessibility settings to reduced settings mode in MXMF

Resolved Issues

- SPR-47094 Resolves an issue where, device does not connect to AirWatch Server when device is connecting to the network through a Proxy PAC file.
- SPR-46408 Resolves an issue where, StageNow Not showing downloading pop up when downloading OS update file from custom ftp server
- SPR-46162 Resolves an issue where, USB keyboard stop working when using USBMgr, a
 parameter called "Access device storage from PC via USB" is set to disable.
- SPR-46418 Resolves an issue where, License through Proxy is failing from StageNow
- SPR-47128 Resolves an issue where, App installed manually to device failed to uninstall via StageNow/EMDK uninstall from App Manager
- SPR-47061 Resolves an issue where MX Upgrade APK will fail
- Fixed an issue where, DataWedge workflow plug-in only allows to do free-form image capture with the default parameters hence any free-form image capture parameter change will not override the default parameters.
- Fixed an issue where, a customer using a proxy PAC file which has isInNet() JavaScript API to direct
 the traffic to intranet vs extranet or similar functionality will not be able to establish a connection to the
 desired endpoint without switching to an alternate API such as dnsDomainIs() or shExpMatch()
 ordnsDomainLevels().



- Usage Notes
 - None

Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	11-27-20.00-RG-U00-STD-GRT-04
Android Version	11
Security Patch level	August 05, 2023
Component Versions	Please see Component Versions under Addendum section

Device Support

The products supported in this release are TC15 series product. Please see device compatibility details under Addendum Section.

Known Constraints

- Due to Google security constraint, products introduced with Android 11 as the base OS limits the "adb push" command to copy files only to /data partition hence pushing files directly to /enterprise or sub folder of enterprise partition using "adb push" command will not be supported. Please see respective product documentation for further details on path changes related to this constraint.
- Camera preview timeout will be same as the Screen time out set in the system.
- When internal storage runs out, while recording a video or taking pictures using the camera App, user is expected to switch default storage location to external SD card (if a SD Card is present) manually.

Important Links

- Installation and setup instructions (if the link does not work, please copy It to browser and try)
- Zebra Techdocs
- Developer Portal

Addendum

Device Compatibility

This software release has been approved for use on the following devices.



Device Family	Part Number		Device Specific Manuals and Guides
TC15	TC15BK-1PE14S-A6 TC15BK-1PF14S-A6 TC15BK-1PF14S-BR	TC15BK-1PE14S-IA TC15BK-1PE14S-ID TC15BK-1PE14S-TK	TC15 Home Page

Component Versions

Component / Description	Version
Acoustic Profiles	TC15: General:TC15-R-1.3 Cellular: TC15-R-1.1
Audio	0.1.0.0
AnalyticsMgr	10.0.0.1002
Android SDK Level	30
Base Band Version	MPSS.HI.4.3.1-01282-MANNAR_GEN_PACK-1
Battery Manager	1.4.1
Bluetooth Pairing Utility	3.29
Camera	2.04.102
Camera Tuning	Camera 0:01.C.OV13B10.18 Camera 1:01.C.GC5035.04
DataWedge	11.4.310
EMDK	11.0.141.4041
Files	Aml_doc_310851020
GMS	[11_202203]
License Manager	License Manager: 6.1.1 License Agent Version: 6.1.7.5.0.3
Linux Kernel	5.4.233
MXMF	13.1.0.14
NFC	NFC_NCIHALx_AR18C0.11.02.00



OEM info	9.0.0.828
OSX	SD6375.110.25.39
QCN	1.0
RIL	Qualcomm RIL 1.0
RXLogger	7.75.5.36
Scanning Framework	37.9.24.0
StageNow	11.9.0.1
Touch Panel (FW)	Version : 0x0a Mode-Finger only
WWAN	HW MBN: HW_DEFAULT: 0AE10104 SW MBN:SIM 0: ROW_Commercial: SW MBN:SIM 1: ROW_Commercial: Autoselection:SIM 0: enabled Autoselection:SIM 1: enabled
Zebra Data Service	10.0.4.1263

Revision History

Rev	Description	Date
1.0	Initial release	June 24, 2023