

# Release Notes – Zebra Android 13

## 13-26-19.00-TN-U00-STD-GRT-04 Release (NON-GMS)

# **Highlights**

This Android 13 GMS release 13-26-19.00-TN-U00-STD-GRT-04 covers TN28 series product. Please see, device compatibility under Addendum Section for more details.

### Software Packages

Package Name	Description
GR_FULL_UPDATE_13-26-19.00-TN-U00-STD-GRT-04.zip	Full Update Package
GR_DELTA_UPDATE_13-23-30.00-TN-U00-STD_TO_13-26-19.00- TN-U00-STD.zip	Delta package from previous release 13-23-30.00-TN-U00- STD-GRT-04

### **Security Updates**

This build is Compliant up to Android Security Bulletin of Feb 05, 2024

### LifeGuard Update 13-26-19.00-TN-U00-STD-GRT-04

This LG patch is applicable for 13-23-30.00-TN-U00-STD-GRT-04version.

- New Features
  - None
- Resolved Issues
  - None
- o Usage Notes
  - None
- o Known Constraints
  - None



### LifeGuard Update 13-23-30.00-TN-U00-STD-GRT-04

This LG patch is applicable for 13-23-30.00-TN-U00-STD-GRT-04version.

Updated below mentioned components. WebView 116.0.5845.114

#### • New Features

- UI Manager adds the ability to Show/hide Immersive Mode pop-up warning.
- Pop-up suppression and USB controlling Application.
- Allows capture of either a barcode or OCR (single word) by centering the desired target with the aiming crosshair or dot. Supported on both Camera and Integrated Scan Engines.

#### • Resolved Issues

- SPR51331 Resolved an issue where Scanner remained in DISABLED status after suspending and resuming the device.
- SPR51244/51525 Resolved an issue where ZebraCommonIME/Data Wedge getting set as primary Keyboard.
- SPR51101 -- Resolved an issue wherein few chars were getting missed in decoded barcode data while performing scanning in HID mode.
- SPR51467 Resolved an issue wherein VoLTE config for a certain carrier was not connecting to 5G.
- SPR48241 Resolved an issue wherein System UI was crashing with MobileIron's DPC launcher on long pressing of back button from keyboard.
- SPR50986 Resolved an intermittent issue wherein Datawedge profile with UPCA settings was not getting created programmatically.
- SPR-51480 Resolved an issue wherein Shift key functionality with ForceStateOFF was not working.

#### • Usage Notes

- None
- o Known Constraints
  - None

### LifeGuard Update 13-21-05.00-TN-U00-STD-GRT-04



#### **New Features**

- This is an initial Android 13 NON-GMS release for TN28 family of products.
- Initial Beta Release of Zebra Showcase App (Self Updatable) explores the latest features and solutions, a platform for new demos built on Zebra Enterprise Browser.
- DWDemo has moved to ZConfigure folder.

#### **Resolved Issues**

- SPR48680 Resolved an issue with Video conference over WEB RTC (Real Time Communication)
- SPR48197 Resolved an issue with Device freeze and reboot after a specific SIM is inserted.
- SPR50196 Resolved an issue with Display randomly blinks off on when in workstation cradle.
- SPR50306 Resolved an issue with intermittently fail to emit scan beam.
- SPR50527 Resolved an issue with reboot with specific carrier.
- SPR51037 Resolved an issue with Scan beam issue.
- SPR50307 Resolved an issue with unexpected reboots.
- SPR50571 Resolved an issue with Manual Screen Rotation Doesn't Rotate the Screen.
- SPR50667 Resolved an issue with Bluetooth disconnections with payment pin terminal.
- SPR50862 Resolved an issue with wrong APN proxy & mms setting for Swisscom fix porting.
- SPR47670 Resolved an issue with Application crashing
- SPR47886 Resolved an issue with Synaptic FW
- SPR48803 Resolved an issue with MX UI Setting LockOverrideButton throws exception Feature is not supported.
- SPR50166 Resolved an issue with Verizon network connection.
- SPR48504 Resolved an issue with access internal site by URL.
- SPR47061 Resolved an issue with MX APK Upgrade.
- SPR47856 Resolved an issue with WLAN disconnection.
- SPR47926 Resolved an issue with Available SSID's are not always showing up / connecting
- SPR50640 Resolved an issue with DUT not able to ping Hostname if changed MX 11.6
- SPR51205 Resolved an issue with DUT seems to have same BT SCO 4kHz.
- SPR47128 Resolved an issue with App installed manually to device failed to uninstall via Stagenow/ EMDK
- SPR47285 Resolved an issue with TN28 enter to Rescue Party mode after called the reboot from MX under DO mode of China Unicom MDM.
- SPR47767 Resolved an issue with ET45 incorrect screen size information shown
- SPR47903 Resolved an issue with ET40 location services crashing.
- SPR47925 Resolved an issue with ET45 display reverting to landscape mode when docked
- SPR48182 Resolved an issue with SOTI script resetpassword is setting screen lock to Password instead of PIN.
- SPR48705 Resolved an issue with ET45 rotating when in cradle.
- SPR51024 Resolved an issue with ET4x Lock Override button is not working.
- SPR50755 Resolved an issue with decomission battery error.
- SPR47768 Resolved an issue with WLAN reconnection issue.
- SPR51024 Resolved an issue with ET4x Lock Override button is not working.

#### **Usage Notes**

None



#### **Known Constraints**

- DHCP Option 119 & Auto PAC Proxy feature is currently not supported in this release. Zebra is working on enabling these 2 features in future Android 13 releases.
- Ethernet configuration static to DHCP is not supported via Mx in this release.
- To apply Delta OTA packages, use StageNow/MDM solution. Delta OTA packages are not supported in Recovery mode.
- Data will not be Persisted if we upgrade to this A13 image from A11 image with greater SPL Version .
- Upgrading to this A13 OS version from A11 will not work on 1mbps network until this issue is fixed in A11 image.
- In mirror mode if device and external display resolution are different, UI flicker will be observed when Undock/ dock the device.
- OTA update from AB /storage/usbotg/ will take more than 2 minutes to initiate.
- In landscape mode when display and font is set to maximum, Lock icon will not be visible .
- Wireless insights and wireless analyzer are not supported in this release. will be supported in a later SW Update
- Workstation Connect is not supported on this release, compatibility with this solution will be introduced on an upcoming release.
- Zebra apps do not support Android Work Profiles or any COPE Mode features. Zebra is working on enabling these features in future Android 13 releases.

#### **Version Information**

Below Table contains important information on versions

Description	Version
Product Build Number	13-26-19.00-TN-U00-STD-GRT-04
Android Version	13
Security Patch level	Feb 05, 2024
Component Versions	Please see Component Versions under Addendum section

### **Device Support**

The products supported in this release are TN28 series product. Please see device compatibility details under Addendum Section.

# **Important Links**



- Installation and setup instructions (if the link does not work, please copy It to browser and try)
- Zebra Techdocs
- Developer Portal

# Addendum

### **Device Compatibility**

This software release has been approved for use on the following devices.

Device Family	Part Number		Device Specific Manuals and Guides
TN28	TN28CKA-1QE14SY- CN TN28CKA- 1QE14SX-CN	TN28CKA-1QG14SY-CN TN28CKA-1QG14SX-CN	TN28 Home Page

# **Component Versions**

Component / Description	Version
Acoustic Profiles	General:TN28-T-2.1 Cellular: TN28-T-2.1
Audio	0.12.0.0
AnalyticsMgr	10.0.0.1006
Android SDK Level	33
Base Band Version	MPSS.HI.4.3.4-00529-MANNAR_GEN_PACK-1
Battery Manager	1.4.7
Bluetooth Pairing Utility	Application Version: 6.3.0 Build Version: 5.3
DataWedge	13.0.121
EMDK	13.0.7.4307
Files	version 13



ZSL	6.0.29
Linux Kernel	5.4.249
MXMF	13.1.0.65
NFC	NFC_NCIHALx_AR18C0.13.01.00
OEM info	9.0.0.1005
OSX	QCT6375.130.13.8.14
RXLogger	13.0.12.27
Scanning Framework	39.67.3.0
StageNow	Application version: 13.0.0.0 Build Version: 13.1.0.65
Touch Panel (FW)	Touch Version: 0x0a Mode: Finger only
WLAN	NA
Zebra Bluetooth Settings	13.0.5
Zebra Camera	2.04.102
Zebra Data Service	10.0.7.1001
Zebra Volume Control	NA
WebView	116.0.5845.114

# **Revision History**

Rev	Description	Date
1.0	Initial release	December 07, 2023