
Release Notes – ET1N2 Android Jellybean Patch for GPS Rollover Fix

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Release Date](#)

Introduction

This Package includes support for GPS week number roll over Patch

Description

Updated to handle extended GPS Week number for correct date calculation due to GPS week number roll over

Contents

SPR37323_ET1N2_JB_GPSRollover_Fix.zip - GPS week number roll over Patch.

New GPS Firmware version	91.101
---------------------------------	--------

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System	BSP Version
ET1 N2	Android JB 4.1.1	BSP 02.20.2529 BSP 02.20.2478 BSP 01.20.2345 BSP 01.20.1651

Installation Requirements

This SW is intended for the ET1 N2 JB devices.

Installation Instructions

1. Copy SPR37323_ET1N2_JB_GPSRollover_Fix.zip to the root directory of SD card.
2. Place the SD card in the device to be upgraded and connect to A/C power.
3. Press and hold the Power button on the device until the Device options menu appears.
4. Tap on Reset to reboot the device.
5. When the device is rebooting hold the right Scan/Action button to enter Recovery update mode.
6. When the Recovery Mode screen appears release the Right Scan/Action button.
7. Tap Home key to access recovery menu screen.
8. Tap P1, P2 keys to navigate to "apply update from /sdcard" option.
9. Tap P3 to select this option.
10. Tap P1, P2 keys to navigate to the update zip file.
11. Tap P3 to select this option.
12. After pressing P3, the upgrade will start.
13. After upgrading successfully, the screen will back to Recovery mode menu.
14. Tap P1, P2 keys to navigate to the "reboot system now" option.
15. Tap P3 to select this option.
16. After pressing P3 system will reboot.

Release Date

June 17, 2019