

Release Notes - MC32N0 CE 7.0 - Premium BSP v00.57.04 - HotFix CFE v02.06.00 Package

- [Introduction](#)
- [Description](#)
- [Package Details](#)
- [Device Compatibility](#)
- [Installation Requirements](#)
- [Installation Instructions](#)
- [Release Date](#)

Introduction

HotFix CFE (Cumulative Fixes from Engineering) Package contains multiple SPR Hotfixes into a single package. The HotFix CFE Package helps the end users to keep up to date with all the SPR hotfixes for given product software release / revision.

HotFix CFE packages are validated only by engineering validation team and the package follows Zebra Technologies HotFix Package Policy. Click here to view HotFix Package Policy. [HotFix Support Policy](#)

Description

CFE package CFE_MC32_CE_005704_EN_v020600_WB.cab / CFE_MC32_CE_005704_EN_v020600_NB.cab file includes the following HotFixes:

SPR No	Synopsis
29949	Device intermittently fails to release and/or acquire the SMSC9500 based Ethernet connection in the Single-slot Ethernet cradle.
29847	Device is Crashing/Freezing inside the cradle at times. Recovery is via a cold boot only.
29685	RDP connection bar scatter when we scroll in RDP session.
28950	Scan Application hangs randomly during scanner enable with recovery being device reboot only.
28945	Can't add printer to Remote Desktop Client.
28536	File manipulation (Copy/Delete) takes more time when \Application folder is mounted as removable storage on Windows 10.

Package Details

CFE_MC32_CE_005704_EN_v020600_WB.cab (CFE package with auto Warm boot)

CFE_MC32_CE_005704_EN_v020600_NB.cab (CFE package without auto Warm boot)

Device Compatibility

This HotFix CFE Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC32N0	CE 7.0	v00.57.04

Installation Requirements

The HotFix CFE cab can be deployed to the Mobile device through any one of the below mentioned methods. For installing the cab, the users should have at least one of the below mentioned tools.

- Windows Mobile Device Center (For Windows Desktops)
- SD Cards / Micro SD cards
- MDM set up

Installation Instructions

For Normal installation of the PATCH:

- Windows Mobile Device Center (For Windows Desktops) Installation Instructions:
 - Copy "CFE_MC32_CE_005704_EN_v020600_WB.cab" file to the Application folder on the device.
 - Deploy the solution by tapping on the "CFE_MC32_CE_005704_EN_v020600_WB.cab" file.
 - After successful deployment of the "CFE_MC32_CE_005704_EN_v020600_WB.cab" file, device will do an automatic warm boot.
- SD Cards / Micro SD cards Installation Instructions:
 - Copy "CFE_MC32_CE_005704_EN_v020600_WB.cab" file to the SD card.
 - Deploy the solution by tapping on the "CFE_MC32_CE_005704_EN_v020600_WB.cab"
 - After successful deployment of the "CFE_MC32_CE_005704_EN_v020600_WB.cab" file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

- Set up MDM (MSP, Soti, Airwatch, etc..) to send "CFE_MC32_CE_005704_EN_v020600_NB.cab" file to the application folder of the device.
- To deploy the solution, setup in MDM to install the cab file "CFE_MC32_CE_005704_EN_v020600_NB.cab" file.
- Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

Release Date

August, 2016