

---

# Release Notes – WT41N0 CE 7.0 Chinese Simplified Hotfix OS v64.57.06

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

## Introduction

---

SPR33867/32707 – Unable to display Chinese characters in Dropdown or in combo list box options when Chinese page is browsed.

This Hot Fix OS v64.57.06 is based on BSP v04.57.05

## Description

---

Resolved an issue wherein Chinese fonts are not displaying on IE browser when using dropdown and combo list by updating an image 41X0BcpUC645706.zip

## Contents

---

41X0BcpUC645706.zip - OSUpdate Package for WT41N0 CE devices including Clean Application

## Device Compatibility

---

This HotFix OS Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
WT41N0	CE 7.0	v04.57.05

Note: This release is applicable for Chinese Simplified OS only.

## Installation Requirements

---

WT41N0 device must contain a released version of CE 7.0

## Installation Instructions

---

1. Unzip the "41X0BcpUC645706.zip" files and copy its content to the \Temp folder.
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \temp\OSUpdate folder and invoke the 41X0c70Bcp\_TEMP.Ink shortcut.
4. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

## Part Number and Release Date

---

N/A

January 2018