
Release Notes – MC2180 CE 6.0 Japanese Hotfix OS v64.34.21

Contents

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

SPR 33503 – Fonts will resize itself after activating the taskbar when taskbar is set to autohide.

This Hot Fix OS v64.34.21 is based on BSP v04.34.0120

Description

Resolved an issue wherein fonts are resizing itself after activating the taskbar by updating an image 2100AjpUP643421.zip

Contents

2100AjpUP643421.zip - OSUpdate package without Clean Application

Device Compatibility

This HotFix Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC2180	CE 6.0	v04.34.0120

Note: This release is applicable for Japanese OS only.

Installation Requirements

MC21 device must contain a released version of CE 6.0

Installation Instructions

1. Unzip the "2100AjpUP643421.zip" file and copy its content to the \Application folder.
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \Application\OSUpdate folder and invoke the 2100c60Ajp_APP shortcut.
4. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

OR

1. Unzip the "2100AjpUP643421.zip" file and copy its content to the \Storage Card folder.
2. Place the SD card in the device to be upgraded.
3. Place the device to be upgraded on A/C power supply.
4. Navigate to the \Storage Card\OSUpdate and invoke the 2100c60Ajp_SD shortcut.
5. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

Part Number and Release Date

N/A

January 2018