Release notes MC319Z RFID Release v2.2.5103 and Update Loader image WEH 6.5 (4.41.004)

Release Notes for Version

Released June 2012

Contents

Introduction	1
Software Download	1
Known issues	2
Questions	2
Disclaimer	2

Introduction

This *Release Notes is* for the MC319Z RFID handhelds RFID release v2.2.5103 and Update loader image release WEH 6.5 (v4.41.0004). This change has been made to accommodate the transition to a new display in the MC319Z RFID handheld devices.

It contains two components

- 1. Updated OS BSP version WEH 6.5 (4.41.004) : To support new display on the handheld devices
- 2. Updated RFID CAB file 2.2.5103 : To support new display on the handheld devices

Software Download

The software download is available at: http://support.symbol.com/

Version	File	Date	Size
4.41.04		May 2012	57893 KB
2.2.5103		May 2012	1492 KB

Important Notes:

This software is applicable for MC319Z RFID Windows Embedded Handheld 6.5 devices. It will update the following two components

- Device OS : Windows Embedded Handheld 6.5 (OEM version 4.41.004)
- RFID software : 2.2.5103

Other salient points:-

- This image upgrade is being released to accommodate the display change on MC319Z devices.
- Devices with new displays will only be able to run BSP version 4.41.004 and higher. They will not be able to run older BSPs.
- This new build will continue to support current existing hardware.
- -

Release notes MC319Z RFID Release v2.2.5103 and Update Loader image WEH 6.5 (4.41.004)

- It is unlikely that existing application software will be impacted by the underlying OS release. However, it is recommended that the application software be tested on this OS prior to deploying on new devices.

RFID features:-

The RFID features in 2.2.5103 are the same as 2.2.5101.

Other:-

- This OS and RFID cab file supports all the variants of the MC319Z RFID handheld devices.

The important version numbers of the new build are as follows.

OEM version	04.41.0004
OS version	5.02.29040
PowerMicro version	68.02.0001
Monitor Lite version	1.22.3010
IPL version	1.04.0000
CPLD version	1.00
Partition version	2.00.0000
OBM version	1.11.000
RFID version	2.2.5103

Known issues

Questions

For sales related enquiries, contact Motorola Inc. at 301 610-6100 (Monday-Friday 8:30 a.m. – 5:00 p.m. EST): http://www.symbol.com/rfid

For technical assistance please call Motorola at 800-653-5350 (24x7 support line): http://www.symbol.com/services/howto/howto_contact_us.html

Disclaimer

While Motorola Inc. has committed its best efforts to providing accurate information in this document, we assume no responsibility for any inaccuracies that may be contained herein, and we reserve the right to make changes to this document without notice.

Motorola, Inc. One Motorola Plaza Holtsville, New York 11742-1300 http://www.symbol.com