Release notes

MC319Z RFID Release v3.2.6004 and Update Loader image WEH 6.5 (v4.41.004)

Release Notes for Version

Released October 2013

Contents

Introduction Software Download	
Known issues	
Questions	2
Disclaimer	2

Introduction

This *Release Notes is* for the MC319Z RFID handhelds RFID release v3.2.6004 and Update loader image release WEH 6.5 (v4.41.0004). This change has been made to improve the battery life of the MC319Z.

It contains two components

- 1. Updated OS BSP version 4.41.004 : To support new display on the handheld devices
- 2. Updated RFID CAB file 3.2.6004 : To support new display on the handheld devices

Software Download

The software download is available at: http://support.symbol.com/

Version	File	Date	Size
4.41.04		October 2013	57 MB
3.2.6004		October 2013	5.36 MB

Important Notes:

This software is applicable for MC319Z RFID Windows Embedded Handheld 6.5 devices. It will update the following two components

- Device OS : Windows Embedded Handheld (WEH) 6.5 (OEM version 4.41.004)
- RFID software : 3.2.6004

Other salient points:-

- This upgrade improves the battery life of the MC319Z. It allows the customer to manage the MC319Z battery life by selecting one of 5 different battery life profiles depending on the RFID read requirements and the optimal battery life desired.
- This is based on and contains all the features of 2.2.5103
- It is unlikely that existing application software will be impacted by the underlying OS release. However, it is recommended that the application software be tested on this OS prior to deploying on new devices.

Release notes MC319Z RFID Release v3.2.6004 and Update Loader image WEH 6.5 (v4.41.004)

- This update includes RapidRead demo software application in the RFID CAB file installer. The shortcut to this application can be located in the Start menu of the MC319Z device.

RFID features:-

- The RFID features in 3.2.6004 are the same as 2.2.5103.

Other:-

This OS and RFID cab file supports all the variants of the MC319Z RFID handheld devices.

The important version numbers of the new build are as follows.

OEM version	04.41.0004
OS version	5.02.29040
PowerMicro version	68.02.0001
Monitor Lite version	1.22.3010
IPL version	1.04.0000
CPLD version	1.00
Partition version	2.00.0000
OBM version	1.11.000
RFID version	3.2.6004

Known issues

Questions

For sales related enquiries, contact Motorola Inc. at 301 610-6100 (Monday-Friday 8:30 a.m. - 5:00 p.m. EST): http://www.symbol.com/rfid

For technical assistance please call Motorola at 800-653-5350 (24x7 support line): <u>http://www.symbol.com/services/howto/howto_contact_us.html</u>

Disclaimer

While Motorola Inc. has committed its best efforts to providing accurate information in this document, we assume no responsibility for any inaccuracies that may be contained herein, and we reserve the right to make changes to this document without notice.

Motorola, Inc. One Motorola Plaza Holtsville, New York 11742-1300 http://www.symbol.com