

MC45 OPERATING SYSTEM BSP 04.17.0004 RELEASE NOTES

INTRODUCTION

This package contains the v04.17.004 English OS images for the MC45 terminals which are running with WEHH 6.5.3 operating system.
This image supersedes the older images.

DESCRIPTION

Changes since BSP 04.17.0002:

SPR28377 – Resolved an issue where MC45 battery won't charge.

Note:

The OS update package does not wipe the application folder. If it is preferred to wipe the Application folder during the OS update, the CleanAppl.bin command should be added to the pkgs.lst file. The CleanAppl.bin file is already included in the OS Update package.

CONTENTS

MC45_BSP04.17.004EN.zip - Update Loader images for English OS 04.17.004

DEVICE COMPATIBILITY

This software release has been approved for use with the following devices.

Device	Operating System
MC45	Windows Mobile 6.5.3

INSTALLATION REQUIREMENTS

This software package has been approved for use with the following:

Microsoft Windows 2000 or Windows XP Operating System

ActiveSync 4.5 or higher.

If developing applications for Windows Mobile 6.5

MC45 currently running English BSP 04.17.0002.

INSTALLATION INSTRUCTIONS

Copy contents of zip file to SD card or to \Temp folder. Execute StartUpdLdr.exe or cold boot terminal by pressing 1 + 9 + pwr and hold the left trigger key to start the update loader process.

PART NUMBER AND RELEASE DATE

459Xw65XenUL041704

April, 2016