

# MC45 OPERATING SYSTEM BSP 04.17.02 RELEASE NOTES

## INTRODUCTION

SPR 27742 - This patch enhances the decode performance for QR symbologies.

## DESCRIPTION

This patch contains the latest decoder library version v6.2.2.24 which has performance enhancement for QR symbologies.

## CONTENTS

SPR27742\_MC45\_W60\_en\_04.17.02\_v1\_0\_NB.cab (Hotfix package without warm boot)

SPR27742\_MC45\_W60\_en\_04.17.02\_v1\_0\_WB.cab (Hotfix package with warm boot)

## DEVICE COMPATIBILITY

This software release has been approved for use with the following Zebra devices,

Device	Operating System
MC459X	WM 6.5

## INSTALLATION REQUIREMENTS

MC45 device with BSP v4.17.02.

## INSTALLATION INSTRUCTIONS

### For NORMAL installation of the PATCH:

Windows Mobile Device Center (For Windows Desktops) Installation Instructions:

1. Copy "SPR27742\_MC45\_W60\_en\_04.17.02\_v1\_0\_WB.cab" file to the Application folder on the device.
2. Deploy the solution by tapping on the "SPR27742\_MC45\_W60\_en\_04.17.02\_v1\_0\_WB.cab" file.
3. After successful deployment of the "SPR27742\_MC45\_W60\_en\_04.17.02\_v1\_0\_WB.cab" file device will do an automatic warm boot.

**For MSP or REMOTE installation of the PATCH:**

1. Set up MDM (MSP, Soti, Airwatch, etc..) to send "SPR27742\_MC45\_W60\_en\_04.17.02\_v1\_0\_NB.cab" file to the application folder of the device.
2. To deploy the solution, setup in MDM to install the cab file "SPR27742\_MC45\_W60\_en\_04.17.02\_v1\_0\_NB.cab" file.
3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

**PART NUMBER AND RELEASE DATE**

N/A

August 2015