

MC45 OPERATING SYSTEM BSP 87.13.001 RELEASE NOTES

INTRODUCTION

The MC45 is a size and cost optimized enterprise mobile computer that will help value conscious enterprises affordably automate business processes in field mobility applications. It offers 3.5G WPA N connectivity, high-performance 1D scanner, a color camera capable of picture taking and enterprise class decoding of 2D barcodes, lightweight design, rugged construction and a core set of mobile computing features at affordable price points.

DESCRIPTION

1. Windows Mobile 6.5.3 AKU 5.2.29128 (Build 29128.5.3.12.16)
2. Fusion Software H_3.40.0.1.057R
3. AirBEAM Client v7.08.42
4. Enterprise Dialer v5.2.5312.27015

CONTENTS

1. 459Xw65XkoUL871301.zip : An UpdateLoader Package contained in a ZIP file.
2. 459Xw65XkoAB871301.apf : A package for deployment using AirBEAM.

DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC45	Windows Mobile 6.5 Professional

INSTALLATION REQUIREMENTS

This software package has been approved for use with the following:

Microsoft Windows XP Operating System or higher.

ActiveSync 4.5 or higher.

If developing applications for Windows Mobile 6.5

INSTALLATION INSTRUCTIONS

Copy contents of zip file to SD card or to \Temp folder. Execute StartUpdLdr.exe or cold boot terminal by pressing 1 + 9 + pwr and hold the camera key to start the update loader process.

BUGS FIXED/CHANGES FROM OS IMAGE 02.13.000

1. Korean localization support.
2. Added warning pop up message everytime the use open the Internet Explorer.
3. Lock UMTS to 2100MHz.
4. Lock the UI for the bands page for UMTS Only.
5. Microsoft Dialer is the default dialer.
6. WZC is set as default.
7. MMS support disabled.
8. Added support for Korean SMS.
9. Added default webpage in Internet Explorer.
10. Added SKT GPRS settings.

PART NUMBER AND RELEASE DATE

Updated September 29, 2013

459Xw65XkoUL871301.zip

459Xw65XkoAB871301.apf