MC9100 OPERATING SYSTEM BSP 80.32.06 RELEASE NOTES

1 INTRODUCTION

The Motorola MC9100 Software release Version 80.32.06 offers the following enhancements over Rev B Software release version 02.32.04

- Built with Dec 2012 QFE Base.
- Resolves Major Customer Issues.

2 DESCRIPTION

General Enhancements/Fixes:

This OS Update Package for MC91xx CE6.0 Package resolves following issues related to customer SPRS:

SPR 23284-

MC3190 CE6 device with BSP32 has an issue during connection between Appcent er 1.10

(Build 2000) RDP client and own remote server, after several attempts the unit stop s responding on keypad and touch screen.

SPR22540-

Using IE navigate to customer URL either over Active Sync or Over WLAN and observe the device getting locked up. Recovery from the lockup is forced warm boot.

SPR22765In MC31xx-

G device using Networking Make a new connection, then goto Security settings, after that enable "preview user name and password" this will cause device to freez e/hang.

3 CONTENTS

9100BenUP803206.zip - OSUpdate Package v80.32.06

9100c60BenAB803206.APF - AirBEAM Package v80.32.06

4 DEVICE COMPATIBILITY

This software release has been approved for use with the following Zebra devices.

Device	Operating System
MC91xx	Windows CE 6.0 Professional

5 INSTALLATION REQUIREMENTS

MC91xx device must contain release version of CE6.0 software.

6 INSTALLATION INSTRUCTIONS

Upgrade to Version 80.32.06 through \Temp

- Unzip 9100BenUP803206.zip upgrade package to local desktop.
- Copy OSUpdate folder and all its contents to \Temp of the device.
- Run 9100c60Ben_TEMP shortcut from \Temp\OSUpdate folder to start the update process.
- The update will takes approximately 2 minutes
 Upgrade to Version 80.32.06 through \Storage Card
- Unzip 9100c60BenUP803206.zip upgrade package to local desktop.
- Copy OSUpdate folder and all its content to root folder on SD card.
- Insert the SD card into a SD slot on a device.
- Run 9100c60Ben_SD shortcut from \Storage Card\OSUpdate folder to start the up date process.
- The update will takes approximately 2 minutes.

7 PART NUMBER AND RELEASE DATE

April 23rd, 2013

9100c60BenAB0803206.APF

9100c60BenUP803206.zip