



Release Notes - Zebra MC92 Android KK LifeGuard Update 11

Highlights

This release contains following software package which is compatible with the MC92 KK product. LifeGuard patches are cumulative and include all previous fixes that are part of earlier patch releases.

Software Packages

| Package Name | Package Description |
|------------------------------------|---------------------|
| CFE-MC92XX-K-00-031308-N-00-11.zip | CFE package update |

Security Updates:

Android Security Patch Level: Mar 5, 2017 (Critical Patch Level: Dec 1, 2021)

Use below link to refer the Android Security bulletin for more information:

<https://source.android.com/security/bulletin/>

CFE v11:

- **CFE-MC92XX-K-00-031308-N-00-11.zip**
1. CVE 2021-1048 Patched the use-after-free security vulnerability which could allow code execution and local elevation of privilege to the kernel from an untrusted application. (SPR 45273)

CFE v10:

- **CFE-MC92XX-K-00-031308-N-00-10.zip**

This release contains following fixes and updates:

1. SPR32676 - Resolved an issue wherein DataWedge crashes due to velocity application profile creation.

CFE v9:

- **CFE-MC92XX-K-00-031308-N-00-09.zip**

Updated below mentioned components:

- Fusion : FUSION_A_4.01.0.0.021

CFE v8:



- **CFE-MC92XX-K-00-031308-N-00-08.zip**

CFE v7:

- **CFE-MC92XX-K-00-031308-N-00-07.zip**

CFE v6:

- **CFE-MC92XX-K-00-031308-N-00-06.zip**

This release contains following fixes and updates:

1. SPR38477 - Resolved an issue wherein devices out of the box intermittently failed to get staged via StageNow.
2. SPR37684 - Resolved an issue where scanned barcode data was being decoded incorrectly intermittently for CODE39 symbology.
3. Updated following Components:
 - MX 7.3.1.1

CFE v5:

- **CFE-MC92XX-K-00-031308-N-00-05.zip**

This release contains following fixes and updates:

1. Updated below mentioned components:
 - Mx: 6.4.1.1
1. SPR36366 - Resolved an issue where MC92 decode support is not proper for code128 barcode in DataWedge.
2. SPR36869 - Resolved an issue where SPR36366 fix causes a noticeable lag before scanner is available after reboot.
3. Scanner Firmware updated (SE4750 firmware - PAABVS00-005-R05 Image kit (IMGKIT_8.02T01.15)

CFE v4:

- **CFE-MC92XX-K-00-031308-N-00-04.zip**

CFE v3:

- **CFE-MC92XX-K-00-031308-N-00-03.zip**

This release contains following fixes and updates:

1. SPR35782 - Resolved an issue where RSSI of the device was reported -2dbm less than the actual value
2. SPR35830 - Resolved an issue where device fails to perform consistent FT roam with certain Infrastructure.
3. Zebra-EULA (End User License Agreement) is included in Android Settings which allows the end user to view the status of Machine Data collection by Zebra Data Service Agent (ZDS).

4. Included Zebra Software License Manager (ZSL) v3.1.1
5. Updated below mentioned components:
 - Mx: 6.4.0.0
 - DW: 6.4.18
 - Fusion : FUSION_A_4.01_0.0.18

CFE v2:

- **CFE-MC92XX-K-00-031308-N-00-02.zip**

This release contains following fixes and updates:

1. Updated DataAnalytics version: 1.0.2.2091
2. SPR33599 - Resolved an issue wherein few system apps were being disabled after Applock whitelist mode was enabled.
3. SPR33512 - Resolved an issue wherein TCPDump rollback was not happening when Change in network connection was detected.
4. SPR33948 - Fixed SSL Exception due to incomplete TLS extension information in client hello packet.
5. SPR34291/34469/34236/34991 - Fixed the issue of double key entries erroneously occurring due to different keyboard sensitivities. (Note: To fix this issue, customer needs to push the attached file (MC92_DOUBLE_KEYPRESS_FIX) to /enterprise/usr folder and reboot the device.

CFE v1:

- CFE-MC92XX-K-00-031308-N-00-01.zip

This release contains following fixes and updates:

1. Spectre & Meltdown correction for variant 2

Version Information

Below Table contains important information on versions

| Description | Version |
|----------------------|--|
| Product Build Number | 03-13-08-4AJ22-K-00-M1-100617 |
| Android Version | 4.4.4 (KitKat) |
| Security Patch level | Mar 5, 2017(Critical Patch Level: Dec 1, 2021) |



| | |
|--------------------|---|
| Linux_kernel | 3.4.48 |
| Component Versions | Please see Component Version under Addendum section |

Important Links

- **Requirements & Instruction:**
 - [Installation and setup instruction](#)
- [Zebra Techdocs](#)
- [Developer Tools](#)

Device Support

This software release has been approved for Android MC92 KK models mentioned below.

| Device | Operating System |
|--------------------|------------------|
| MC92N0-GA0SYxAA6WR | Android 4.4.4 |
| MC92N0-G30SYxAA6WR | Android 4.4.4 |
| MC92N0-GM0SYxAA6WR | Android 4.4.4 |
| MC92N0-GL0SYxAA6WR | Android 4.4.4 |
| MC92N0-GJ0SYxAA6WR | Android 4.4.4 |
| MC92N0-GP0SYxAA6WR | Android 4.4.4 |

Addendum

Component Version

| Component / Description | Version |
|-------------------------|-------------------------------|
| Product Build Number | 03-13-08-4AJ22-K-00-M1-100617 |
| Android SDK Level | 19 |
| Patch Version | 11 |
| App Gallery | 3.0.1.7 |
| B2M Elemez | 1.0.0.352 |
| Battery Manager App | 1.3.7 |
| Bluetooth Stack | 4 |

| | |
|----------------------------|------------------------------|
| BT Pairing Utility | 3.3 |
| Data Analytics | 3.7.1.1002 |
| DataWedge | 6.5.61 |
| Device Diagnostics | 1.15.0.4 |
| DWDEMO | 2.0.11 |
| EA | 2.57 |
| EMDK | 6.6.14.914 |
| MX /OSX | 7.3.1.1/ TI_OSX_4.5-3 |
| PTT | 3.1.32 |
| RXlogger | 3.0.0.53 |
| Scanner Framework | 6.36.0(7.0.1T08.31Kepler_47) |
| SE4750 firmware | PAABVC04-001-R02D0 |
| SOTI | 12.2.0 Build 23434 |
| SPAM | 4.1 |
| StageNow | 2.7.2.1039 |
| Terminal Emulation | 2.0.18.4977 |
| Velocity | 1.2.109.17236.1d65d9c |
| VM Rapid Deployment Client | 07.08.86 |
| Fusion | FUSION_A_4.01.0.0.021 |
| Zebra Volume Control | 1.1.15 |
| Zebra License Server (ZSL) | 3.1.1 |



Revision History

| Rev | Description | Date |
|-----|-----------------|--------------|
| 1.0 | Initial Release | Dec 27, 2021 |