
Release Notes – MC92N0 CE7.0 with SE4750 Scan Engine SW v00.55.13

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

OS Update Package v00.55.13 is a software update for MC92N0 CE7.0 devices using the SE4750 scan engine. This version adds support for the SE4750 scan engine.

Description

1. Operating System: CE7.0
2. CPU Speed OMAP4430 ES2.3 - 1GHz
3. FLASH – eMMC 2GB/1GB
4. SDRAM - LPDDR2 1GB/512MB
5. Microsoft QFE September 2014, Build 2844, Updt39
6. Added SE4750SR, SE4750MR, SE4750HD Scan Engines support
7. Fusion Radio SW suite 2.02.0.0.019R, ROW4
8. BT:
 - Microsoft – 4.0
 - BT Explorer SS1 2.1.1 Build 28342
9. RD Client v7.08.42

Contents

92N0C70BENUP005513.zip	MC92N0 CE7.0 OS Update Package v00.55.13
92N0c70BenAC005513.APF	MC92N0 CE7.0 Airbeam Package v00.55.13
92N0c70BenOS005513.hex	MC92N0 CE7.0 OS Hex Image v00.55.13

Device Compatibility

This software release has been approved for use with the following Zebra devices.

Device	Operating System
MC92N0	Windows CE 7.0

Installation Requirements

MC92N0 device must contain released version of CE7.0 Software.

Installation Instructions

1. Unzip ZIP file and copy its content (OSUpdate folder) to the \Storage Card folder
2. Place the SD card in the device to be upgraded
3. Place the device to be upgraded on A/C power supply.

4. Navigate to the \Storage Card\OSUpdate and invoke the 92N0c70Ben_SD shortcut

OR

1. Unzip ZIP file and copy its content (OSUpdate folder) to the \temp folder
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \temp\OSUpdate folder and invoke the 92N0c70Ben_TEMP shortcut

The update will take about 5 minutes to complete. Please do not remove the device from A/C power during this time.

Part Number and Release Date

92N0C70BENUP005513
92N0c70BenAC005513
92N0c70BenOS005513

16 July, 2015