
Release Notes - MC95X8 01.19.13

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

The Motorola MC9500-K raises the bar for premier rugged mobile computing, incorporating breakthrough ergonomic design and features to support the most demanding field mobility applications. Truly in a class of its own, this groundbreaking device is as different on the inside as it is on the outside. Building on Motorola's signature MC9000 Series, the MC9500-K delivers a more rugged design, more data capture options, true WAN technology independence and application flexibility through customer-swappable WAN subsystems and keypads, more processing power and a game-changing approach to battery and backroom management — all in a lighter, sleeker and easier-to-use form factor.

Update Loader Image 01.19.13 contains the SW required to update an MC95X8 CDMA Phone device which supports the CMI display on RevA HW (128MB RAM/ 512MB Flash).

This software is intended to be loaded and run on the MC95X8 Phone devices. It is important that care be taken to match the device configuration with the appropriate Update Loader package. If an incorrect Update Loader package is loaded, the device may not boot and/or the radios may fail to operate.

Description

v1.19.13

1. CMI display support for MC9598 low memory 128MB RAM/ 512MB Flash configuration terminals.
2. CPLD v5.02 must be loaded on RevA HW with CMI terminals.
3. Includes entire features/enhancements/fixes of v1.19.11 RevA release which are as follows.

- AKU 1.5.2 (Build 20963)
- Fusion Software 3.00.0.0.310R
- BT Explorer v2.1.1 build 26835
- AirBEAM Client v 5.93
- RD Client v 5.93
- GPS Mux v 2.39.4
- Power Micro 55.56.18
- CPLD 5.0
- MC5727 EVDO Rev 3.0 Modem
 1. FW 1.67.02
 2. RIL 3.10.320963.0

4. RHA 0.37

Contents

1. 95x8w61HenUL011913.zip – An UpdateLoader Package contained in a ZIP file. Use Instructions are contained within the ZIP file.
2. 95x8w61HenAB011913.APF – A package file for deployment using AirBEAM.

Device Compatibility

This software release has been approved for use with the following Motorola devices.

Device	Operating System
MC95X8	Windows Mobile 6.1 Professional

Installation Requirements

MC95X8 device must contain a released version of WM6.1 Software.

Installation Instructions

Please see INSTRUCTIONS.TXT in the UpdateLoader Package ZIP file

Part Number and Release Date

Jan 28, 2015

95x8w61HenUL011913.zip
95x8w61HenAB011913.APF