# Release Notes – TC55 Android JB – LifeGuard KRACK Fix Update 01 Release

#### Contents

Introduction

**Component Description and Version** 

Package Details

**Device Compatibility** 

**Installation Requirements** 

<u>Installation Instructions</u>

Release Date

#### Introduction

This release contains the KRACK fix software package which is compatible for TC55 JB GMS and Non-GMS following BSP version.

BSP Version	
BSP 1.09	

SPR33482\_TC55\_JB\_XX\_EN\_KRACK.zip

#### **Fixes:**

Corrections for KRACK vulnerabilities applied.

# Component Description and Version:

Version
TC55 JB
4 1 2

# Package Details

SPR33482\_TC55\_JB\_XX\_EN\_KRACK.zip

#### **Device Compatibility**

This CFE package software release has been approved for use with the following Zebra devices.

Device	OPERATING System
TC55	JB 4.1.2

# Installation Requirements

This SW is intended for all the TC55 JB devices only.

- ADB installed on the PC (including adb drivers)
- USB debugging turned ON (from Developer options)

#### **Installation Instructions**

1. Connect the USB cable from your PC to the device and enable USB mass storage mode on the device.

- On your PC, you should see an internal and external USB mass storage drive (SD card)
  appears in the File Explore and copy "SPR33482\_TC55\_JB\_XX\_EN\_KRACK.zip" file to any
  storage.
- 3. Press and hold on the device the Power button, Scan/Action button and Vol+ until the screen is turned OFF.
- 4. Release the Power and Scan/Action buttons and continue to hold Vol+ button.
- 5. The device should enter to Recovery update mode.
- 6. Release Vol+.
- 7. Click on Vol+ or Vol- to navigate and select appropriated storage.
- 8. Click on Scan/Action button to select the option.
- 9. Click on Vol+ or Vol- to navigate to the patch file.
- 10. Click on Scan/Action button to select the patch file.
- 11. Device will automatically reboot and will be ready to use.
- 12. There is way to Check After installed the SPR33482\_TC55\_JB\_XX\_EN\_KRACK.zip patch in the device.
  - File Browser->system/patch/SPR33482\_TC55\_JB\_XX\_EN\_KRACK-Fix.txt

#### Release Date

Nov 2017