

# **Release Notes - TC55CH Android JB - BSP v01.06.01\_3G - "MEID is not being retained" - SPR 27758**

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

---

## **Introduction**

MEID in Device Setting is not being retained in non-GMS units.

## **Description**

The provided patch allows the device to retain the MEID in non-GMS units.

## **Contents**

SPR27758\_TC55\_JB\_en\_1.6.1\_3G\_nGMS\_v1.0.zip

## **Device Compatibility**

This software release has been approved for use with the following Zebra devices,

Device	Operating System	OEM Version
TC55CH	Android JB 4.1.2	v01.06.01_3G

## **Installation Requirements**

This SW is intended for the TC55 device running non-GMS 01.06.01\_3G build only.

## **Installation Instructions**

1. Connect the USB cable from your PC to the device and enable USB mass storage mode on the device.
2. On your PC you should see an internal and external USB mass storage drive (SD card) appears in the File Explorer and copy the "SPR27758\_TC55\_JB\_en\_1.6.1\_3G\_nGMS\_v1.0.zip" file to any storage.
3. Press and hold on the device the Power button, Scan/Action button and Vol+ button until the screen is turned OFF.

4. Release the Power and Scan/Action buttons and continue to hold Vol+ button.
5. The device should enter to Recovery update mode.
6. Release Vol+.
7. Click on Vol+ or Vol- to navigate and select appropriated storage.
8. Click on Scan/Action button to select the option.
9. Click on Vol+ or Vol- to navigate to the "SPR27758\_TC55\_JB\_en\_1.6.1\_3G\_nGMS\_v1.0.zip" file.
10. Click Scan/Action button to select the recovery update zip file.
11. Device will automatically reboot and will be ready to use.

## **Part Number and Release Date**

N/A  
June, 2015